

SERVICE CHANGE

2) Change on Blade Clamp from S/N 1,184,922E for Type 2; S/N 126,599 and up for Type 3.




FIG.	DESCRIPTION	TYPE 1	TYPE 2	TYPE 3
8	Slider	Part #163191-9 (Discontinued)	Part #163340-8 (Discontinued)	Part #163357-1
32	Blade Clamp	Part #321642-0	Part #322502-9	Part #313067-2 (See Service Change 6)
63	Spring Pin	Part #258009-8 (3.5 - 12)	Part #258018-7 (2.5 - 9)	-----
73	Pin 3	-----	Part #256701-0	-----
74	H.S. Bolt M5x14	-----	-----	Part #265986-A (See Service Change 6)

The above parts are interchangeable as a set.

3) Change on Switch from S/N 1,001.




FIG.	DESCRIPTION	TYPE 1	TYPE 2
58	Switch	Part #651314-6	Part #651271-8
59	Dust Cover	Part #421145-5	Part #411852-8 (See Service Change 4)

Use 650 2066

The above parts are interchangeable as a set.