


PORTER-CABLE



BELT SANDER

WARNING: Electrical repairs should only be attempted by trained repairmen. Contact the nearest Porter-Cable Service Center or other competent repair center.



MOVE FROM EARLY MODEL

ADD TO CURRENT MODEL



*** #863624 Sleeve reduces seal bore in frame #841033 to accept new seal. Press sleeve to stop in bearing bore of frame.